B.R No. 398/2013-14 Dated: 29.11.2014

Inspection report for the Work of: Providing Chain Link Fencing to Storm water Drain Selected Reaches in Ward No. 10, (Doddabommasandra) Vidyarnyapura Sub Division.

By,

Sri K. Manjunath

Inspection Report

Name of Work	: Providing Chain Link Fencing to Storm water Drain at Selected Reaches in Ward No. 10, (Doddabommasandra) Vidyarnyapura Sub Division.
Work Order	: EE/BTP/BBMP/E-TND-05(38)/WO/219/2012-13 Dated: 26.12.2012
Agency	: N.N. Srinivasaiah
B.R. No & Date	: 398/2014-15 Dated: 29.11.2014
Bill Amount	: 10,11,398.00
Job Code	: 010-12-000002
P. Code	: P-0546
Date of Inspection	: 25-02-2016

The above said work was shown to me by the Concerned Ward Engineer.

The work is inspected by me along with the Concerned Ward Engineer Sri Madhavarao.

The work done is Satisfactory

Radha
AE

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Providing Chain Link Fencing to Storm Water Drain at Selected Reaches in Ward No. 10, Doddabommasandra



- Chain Link Fencing



- CC Drain

Zadha
AE

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Jadha
AE

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

AE

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Jadha
AE